



MAHANAND DAIRY

MRSDMM MAHARASHTRA RAJYA SAHAKARI DUDH MAHASANGH MARYADIT
Unit No. 12, Aarey colony, Western Express Highway, Goregaon (E), Mumbai-400065

ENQUIRY

Ref.No.MND/6/ENGG/2023-24 / 2588

Date: - 29/01/2024

Under Postal Certificate

30

TO,

M/S. _____

Dear Sir,

Kindly submit your lowest offer for the following work mentioned below. Quotations may please be sent to us on or **before 09/02/2024**. Quotation received after the due date mentioned herein will not be considered. Quotation should be send in sealed cover duly marked as **Quotation for :- REPLACEMENT OF REFRACTORY FRONT SMOKE BOX OF OUR FOR IAEC BOILER NO:- MR-10753**

Sr. No	Description	Quantity Required
1	<p><u>REPLACEMENT OF REFRACTORY FRONT SMOKE BOX OF OUR FOR IAEC BOILER NO:- MR-10753</u></p> <p><u>SCOPE OF WORK :-</u></p> <ol style="list-style-type: none">1) Party should Remove the existing defective Refractory.2) Party should strengthening the complete smoke box by welding suitable M.S. Plate from inside and outside3) Party should supply and fixing high tensile bolts of suitable length from inside for locking front door.4) Party should supply and fixing high temperature resistant (600°C)Bricks and Refractory cement to cover the front smoke box.5) Party should chipping and reserving loose plaster inside Burner area.6) Party should supply and fixing high temperature cement inside Burner area.7) Party should supply and fixing high temperature cement Blocked 25mm thick around Burner area <p>Note:</p> <ol style="list-style-type: none">1) Rates should be inclusive of all taxes, PF, ESIC, Labour material Transport2) Payment will be made after satisfactory completion of job after getting necessary approvals from counseled authorities3) Party can Visit site if Required4) Vender to bring his Own tools, labour and all materials to Complete the above work	1 JOB


A/C Manager (Engg.)